Annexure D

BUILDING SAFETY CERTIFICATE

No. 1408

Dated: 10 - 03 - 2025

It is certified that the existing building .Sarvhitkari Vidya Mandir (Senior Secondary) , Dhura(Dhuri) ... (name of the building or premises) at ... Village - Dhura, P.O - Harchandpura, Tehsil - Dhuri, Distt.- Sangrur, Pin Code - 148024... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the	02	01				
Block	Ground Floor First Floor	Ground Floor				

with rule and subject to compliance of the specific conditions as appended.

- The parameter to check the stability and safety of building such as structural design ,Architectural drawing, Bearing capacity, Foundation details, Structural drawings, Technical specifications, Test reports of material used and quality control reports are not available.
- 2. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
- 3. A separate certificate regarding fire fighting should be obtained from the competent Authority.
- A separate certificate regarding Electrical works should be obtained from the competent Authority.

Issued on31-05-2024...... at PWD B&R, Malerkotla by Sub-Divisional Engineer Const. Sub-Division No.2 PWD B&R, Malerkotla

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name: Fr. Mohnish

Designation: C.D.E

Name & Address of Department/ Office:

Sub-Divisional Engineer Const. Sub. Div. No. 2

PWD B&R Maierkotla